

MULTI-POINT VEHICLE INSPECTION

Sample

11/5/2020

Repair Order: 1

Service Advisor: Dealer SM

2021 Vehicle Make Model

SUV/Crossover

VIN: 1GYS4JKJ6KR102419

Odometer: 23,444 mi



✔ Checked and OK ⚠ May Require Attention Soon ✖ Requires Immediate Attention — Not Inspected

ONSTAR DIAGNOSTICS

- ✔ OnStar Active
- ✔ Enrolled in Advanced Diagnostics Report
- ✔ Enrolled in Dealer Maintenance Notification
- ✔ Service History/Recall Check

ENGINE OIL & FILTER

- ✔ Engine oil
- Oil life monitor 61%
- Reset oil life monitor

LIGHTS

- ✔ Exterior lights

WINDSHIELD & WIPERS

- ✔ Wiper blade-driver
- ✔ Wiper blade-passenger
- ✔ Wiper blade-rear
- ✔ Windshield condition

BATTERY

- ✔ Battery test results*
- ✔ Battery visual inspection
- ✔ Battery cables & connections

SYSTEMS, FLUIDS & VISIBLE LEAK INSPECTION

- ✔ Engine oil
- ✔ Transmission
- ✔ Drive axle
- ✔ Transfer case
- ✔ Engine cooling system
- ✔ Power steering
- ✔ Fuel system
- ✔ Brake fluid reservoir
- ✔ Windshield washer fluid

TIRE INSPECTION

Driver Front psi before 38 psi set to -- ✔ Tread depth 8/32 or greater — Wear pattern/damage	Passenger Front psi before 34 psi set to -- ✔ Tread depth 8/32 or greater — Wear pattern/damage
Driver Rear psi before 38 psi set to -- ✔ Tread depth 8/32 or greater — Wear pattern/damage	Passenger Rear psi before 37 psi set to -- ✔ Tread depth 8/32 or greater — Wear pattern/damage
— Rotation needed — Alignment needed — Balance needed	— Reset tire pressure monitor — Tire sealant expiration date:

BRAKES

Brakes: Good: 7mm or greater OK: 6mm to 4mm Bad: 3mm or less

Front Brakes ✔ Driver front 7mm or greater (OK) ✔ Passenger front 7mm or greater (OK)	Rear Brakes ✔ Driver rear 7mm or greater (OK) ✔ Passenger rear 7mm or greater (OK)
✔ Brake system	✔ Parking brake

VISIBLE & FUNCTIONAL INSPECTIONS

INSPECT (FIT, FORM, & FUNCTION)

- ✔ Safety belt components
- ✔ Exhaust system
- ✔ Accelerator pedal
- ✔ Passenger compartment air filter
- ✔ Engine air filter
- ✔ Hoses
- ✔ Belts
- ✔ Shocks and struts
- ✔ Steering components
- ✔ Axle boots or driveshaft & u-joints
- ✔ Compartment lift struts
- ✔ Floor mat secured, no interference with pedals

CHECK OPERATION

- ✔ Horn
- ✔ Ignition lock
- ✔ Starter switch
- ✔ Evaporative control system

LUBRICATE

- ✔ Chassis components

*Courtesy battery testing can provide early warning of a potential battery failure. More extensive testing and analysis may be necessary to verify the actual need for battery replacement and/or warranty reimbursement.

Copyright 2020 General Motors. All Rights Reserved. All text, images and other content in this document are subject to the copyright and other intellectual property rights of GM. These materials may not be reproduced, distributed, or modified without the express written permission of GM.

All information provided as a part of this Multi-Point Vehicle Inspection will be used in accordance with the GM Privacy Statement found at www.gm.com/privacy.